

Water Quality Noncompliance Notification
See back of Form for Guidance for Completion

Unauthorized Discharge **Reportable Effluent Violation** **Other**

General Information

Entity Name: Telephone No (#####):
 Permittee TCEQ Region: County: *Permit Number:
 Subscriber

Noncompliance Summary

Description and Cause of Noncompliance (include location, discharge route, and estimated volume of unauthorized discharge):

UPDATE...Sewer overflow caused by a leaking 16" force main at Lift Station (LS) 20 (Q07FM32596 at 1001 Leadership Place. Estimated revised volume for the entire event was 245,000 gallons of liquids. Discharge route was South into North Reese Creek.

Duration:

Start Date: End Date: Or Date Expected to be Corrected:
Time: Time:

Potential Danger to Human Health and Safety or the Environment:

Unknown

Actions Taken

Monitoring Data: Data should be attached or submitted to TCEQ when available.

Field Measurements **Laboratory Samples** **Fish Kill (If yes, estimated number killed):**
 Yes No Yes No Yes No

Actions Taken to Mitigate Adverse Effects:

Used all 3 City of Killeen Vacuum Trucks and 3 additional vacuum trucks from S & M Vacuum & Waste Service to pull over 240 loads of sewer from the upstream Lift Station, LS 22, which significantly decreased the amount of sewer leaking from the broken force main at LS 20. TTG Utilities of Gatesville, took over the jobsite on 6/5/23 and worked over 36 hours until the force main was repaired.

Actions Taken to Correct the Problem and Prevent Recurrence:

Notified the City's Environmental Service Division, the City's Emergency Management Department, the Bell County Emergency Management Department and TCEQ. The City's Public Works and the Water & Sewer staff will continue work on methods and procedures to prevent this from happening in the future.

Verification Information

Information Reported By (Name/Title): Date Reported:

Signature:

Note: If this form is being used for a 5-day written report, a copy of the form should be sent to the TCEQ Region Office, and the original to: TCEQ, Compliance Monitoring Team (MC224), Enforcement Division, P.O. Box 13087, Austin, TX 78711-3087.

* If the noncompliance is an unauthorized discharge from a wastewater collection system, use the permit number of the treatment plant to which the collection system is tied. If you are uncertain of this permit number, you may call the TCEQ Regional Office for assistance.